

Coundon Wedge Site Photos (06.04.23)

Vehicle access to adjacent field from North Brook Road



Lowering area 1- scrub/tree removal



View across paleochannel to wet grassland to be reconnected and location of footbridge to be installed

Access to this part of the site is largely dry and even ground.



View down the western side of the paleochannel in the southern field (access to lowering 2 area)

Ditch running under hedge in between the two fields can sometimes be a bit boggy but at the time of year of delivery should be dry



Lowering area 2 and location of footbridge to be installed

This area can be a bit boggy when it rains heavily, especially with the footpath running through, but is dry for most of the year



Area just south of lowering 2, where paleochannel will be reconnected

